

Guidelines

Steel Roof Coating in an Aggressive Environment – Fruit and Grain Acids and Oils

Surface Preparation

1. Wash surface using high pressure hot water >3000 Psi. with a commercial and detergent. Rinse thoroughly with clean water.
2. Thoroughly inspect surface thoroughly to ensure complete removal of all contamination, and oil. Re-wash any surface as required to completely clean the surface.

Primer Coat

3. Apply one coat of high build two pack Nutech Epoxy Primer A at _____ square metres per litre. Ensure minimum time between cleaning and application of primer to prevent re-contamination of the surface.
4. Thoroughly inspect the surface of the Epoxy coating to ensure complete coverage and no pin holing, bubbling or blistering.

Top Coat

5. Within 24 hours of applying Primer Coat, apply one coat of two pack Nutech Urethane # 2 at _____ square metres per litre.

Maintenance

6. Wash surface regularly (at least once per month) to prevent build up of contaminants using high pressure water and detergent.